

Office of the Assistant Executive Engineer, Public WorksDepartment, Sub - Division, Davanagere.

Old P.B. Road, Davanagere Telephone No. 08192-259676

No: AEE/PWD/S.D/DVG/AE-2/Stability/2023-24/ 1065

Date: 08/09/2024

To,

President, Anmol Public School, Anmol Educational Association ®, Shiramagondanahalli, Davangere-577005.

Sir,

Sub:- Issues of building stability Certificate.

Ref:- Your office letter no. Anmol/2023-24/07, Dated: 31.01.2024.

* * * * *

With reference to the above subject and reference letter the said building was inspected on 07.02.2024 It is certified that the building in which "Anmol Public School" at Shiramagondanahalli is structurally stable and found to be good with respect to quality and as per structural drawings submitted by your self and we said to maintain the school building in good condition every year. This letter is issued with reference to above letter & Challan Number: CR0224005900062471, Dated: 05.02.2024.

Yours Faithfully,

Assistant Executive Engineer, P.W.D. No:3, Sub - Division, Davangere.

BUILDING SAFETY CERTIFICATE

No.

Dated:

Certified that the existing building <u>Anmol Public School</u> (name of the building or premises) at <u>Shiramagondanahalli, Davangere-577005</u> (address) comprised of <u>R.C.C Columns with</u> <u>Footing & R.C.C Plinth Beam</u> basements (s) and <u>Ground+3-Floor R.C.C Building</u> (upper floors) owned/occupied by <u>Anmol Public School</u> (name of the institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by on <u>07-02-2024</u> (date of inspection) in the presence of <u>Sri Dinesh C.G. President</u>, <u>Shiramagondanahalli, Davangere-577005</u> (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes <u>1 to X</u> (X/ XII) with effect from <u>07-02-2024</u> for a period of <u>One</u> years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Regular Maintenance of buildings and School premises should be carried out.

Issued on <u>07-02-2024</u> at <u>Davanagere</u> By <u>Assistant Executive Engineer</u>, <u>P.W.D.</u>, <u>Sub Division</u>, <u>Davanagere</u>.

* Strike put whichever is not applicable.

Signature with Seal Name Designation

Assistant No. 3, P.V.D. Sab-Division, Davangere

Name & Address of Department/ Office:

(Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed/ issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

Format for Application to be submitted by the Educational Organizations

| 1 | Name and address of the building | Anmol Public School Shiramagondanahalli, Davangere – 577005 |
|----|---------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| 2 | Number of stories approved in the sanction building Plan | Ground + 3 Floors |
| 3 | Year of construction | 2005 |
| 4 | Submission of Following documents are not mandatory for the building already constructed and working. But mandatory for new buildings | |
| a) | Approved building plan from the competent authority | Enclosed / Not enclosed |
| b) | Completion certificate duly signed by the supervision Engineer who is in charge of the building | Enclosed / Not enclosed |

STAUS President

Date: 07/02/2024

Anniel Educational Association Shiramagondanahalii, Davangere (Seal and Signature of the Organization)

Place: Shinnagouda yaballi

Remarks of the Inspecting Authority

This School Building inspectial on 4th Jeb 2024. ... School Building found stree durally stable and good Conditions and we teld to president of School to maintain every year in good condition and to paint to School touilding is early of pathole

> Assistant Executive Engineer No. 3, EW.D. Sub-Division, Davangere (Seal and Signature of the Authority)